

## DRIVERS DIRECTORY

RITOUCH.EXE	Driver
LINEAR.EXE	Linearization program ( -4, -9, -25 points )
FREEDRAW.EXE	Drawing test

## TOOLS DIRECTORY

DIRTOOL.EXE	Program used to install driver
-------------	--------------------------------

## INSTALLATION

Execute "install.bat [DESTDIR]", and it will do as follows

- (1) copy files to hard disk, and
- (2) modify/create C:\AUTOEXEC.BAT

ex. "INSTALL C:\" creates directory C:\RITOUCH into which files listed above will be copied, and C:\AUTOEXEC.BAT will be appended with:

```
SET PATH=%PATH%;C:\RITOUCH
RITOUCH.EXE
```

### **Note!**

Execute "TPANEL /?" for more details.

## UNINSTALL

- (1) Restore C:\AUTOEXEC.BAT with  
copy C:\AUTOEXEC.RIT C:\AUTOEXEC.BAT
- (2) Delete all files copied with  
deltree C:\RITOUCH <--- (where you installed driver)

## LINEARIZATION

- (1) 9 points linearization, command as the following  
C:\>linear com1 9600 9
- (2) 4 points calibration, command as the following  
C:\>linear com1 9600 4
- (3) 25 points linearization, command as the following  
C:\>linear com1 9600 25

## DRAWING TEST

Drawing test, command as the following

```
C:\>Freedraw com1 9600
```