

QNX USB Driver Installation Note

Revision : 1.3.8408
 OS : QNX Neutrino RTOS v6.3
 Release Date : 12-08-2008

File List:

1. eeti_devi
2. devu-touch-mouse
3. ap

Steps:

1. Copy eeti_devi, devu-touch-mouse and ap to /usr/photon/bin directory.
2. Change the permissions and make the three files executable.
3. Edit /etc/rc.d/rc.local and add the following commands:

```
ph
io-usb -d uhci <-- please modify xhci according to your platform
sleep 2
/usr/photon/bin/eeti_devi
/usr/photon/bin/devu-touch-mouse
```

4. Change the permissions of rc.local and make it executable.
5. Reboot and try to touch the touch screen.

Troubleshooting:

The touch point is not the position I touched.
 Please execute ap and do calibration.
 You can use drawtest to test your calibration result.

Touch can't work

Please use the system process inspector to check whether io-usb, eeti_devi and devu-touch-mouse processes are executing.
 If io-usb exists, eeti_devi or devu-touch-mouse don't exist
 --> please slay existing eeti_devi or devu-touch-mouse and re-load eeti_devi and devu-touch-mouse